



1) Locate the position of the hole on the back of panel Use an outlet box as a template by pressing it into the fiberglass




Location of outlet hole to be cut


2) Cut the fiberglass out being careful not to cut through the fabric facing



3) Cut the fabric diagonally across the hole (in the shape of X)



4) Adhere strip of fabric around the exposed edge of the hole before wrapping the excess fabric from the face around the edge to the back of panel



(Note: Cutting fabric diagonally and wrapping it around the edge will leave a void in the corner • thus the reason for the extra strip of fabric)